

# **Discovery Environmental Inspection Report**

	nation	Project Contact Informa	
Environmental Safety OfficeSchoolEnvironmental Solutions, I13306 Old Marlboro Pike6114 Drum Point RdUpper Marlboro, MD 2077244,644Ft²301-952-6760410-867-6262alex.baylor@pgcps.orgzack@esi4u.com	Certified Indoor Environmentalist Environmental Solutions, Inc. 6114 Drum Point Rd Deale, MD 20751 410-867-6262	School	Environmental Specialists Environmental Safety Office 13306 Old Marlboro Pike Upper Marlboro, MD 20772 301-952-6760

# **Property Location**

6700 Glenn Dale Rd, Glenn Dale, MD 20769

**Date of Inspection:** 4/2/2019



Prepared By: Zack Butcher

Certified Indoor Environmentalist (CIE)

#### Dear Mr. Baylor,

The results of the inspection and testing performed at Glenn Dale Elementary School are concluded, and the findings are enclosed. I want to thank you for allowing ESI the opportunity to service your indoor environmental needs. Included in this report are the observations, lab results, and recommendations from ESI's 04/02/2019 inspection and testing.

#### **Background Information**

The Prince Georges County Public School Environmental Team has taken a proactive approach in cleaning the above-mentioned school to ensure there are no health or environmental risks related to microbial and biological hazards. Historically elevated levels of humidity, condensation from pipes, periodic steam leaks and outdated HVAC systems, may have contributed to water damage ceiling tiles and colonization of mold spores in various area of the school.

#### **Purpose**

ESI was engaged to inspect the school in a random and sufficient manner. Classrooms, administration offices, and common area building materials and contents will be visually inspected for signs of water damage and microbial growth.

In each location inspected, the indoor air quality will be tested for elevated levels of carbon dioxide and carbon monoxide, in addition to measuring the relative humidity and temperature. Microbial hazards within the breathable air space will also be tested.

Based upon the visual assessment, instrument readings, and lab results, ESI will determine if additional remediation in required.

#### **Observations and instrument readings**

The following table is designed for this project. Some of the fields may not be filled in due to not being applicable during the time of the inspection. You will notice either a 'YES' or 'NO' in the table. 'YES' indicates that mold and/or water damage was detected and 'NO' indicates it was not. If 'YES' is noted, remediation recommendation will be included for the area inspected.

Location	IAQ	Swab	R/H	Temp	CO2	Со	Cubic f	eet of air.	
	Sample #								
10	2434292	N/A	28.4%	67.1°	1,137	0.00	6,	800	
			J	inspected	,				
Ceiling	Walls	Teachers	Children's	Tables	Cabinets	Convector	HVAC	Windows	
Tiles		Desk	Desk		Shelving		Diffusors		
2x4	CMU	1	1	10	7	0	4	2	
YES	NO	NO	NO	NO	NO	N/A	NO	NO	
			Obse	rvation N	lotes				
• Ther	e was one wa	ater stained o	ceiling tile.						
• The	Carbon Diox	ide (CO2) le	evel in this ro	om was e	levated at 1	,137 ppm (pa	rts per millio	on).	
• The	indoor air qu	ality should	not pose heal				-		
ident	tified in the b	reathable air	space.						

#### Recommendations

- Remove, discard, and replace the one water stained ceiling tile.
- To reduce Carbon Dioxide (CO2) levels, increase air exchange within this classroom. Ventilating or circulating the air with a fan will also reduce Carbon Dioxide (CO2) levels.

Location	IAQ	Swab	R/H	Temp	CO2	Со	Cubic f	eet of air.
	Sample #							
3	2434293	N/A	17.1%	75.1°	781	0.00	6,	600
			Ι	nspected				
Ceiling	Walls	Teachers	Children's	Tables	Cabinets	Convector	Window	Windows/
Tiles		Desk	Desk		Shelving		Units	Doors
2x4	CMU	0	0	5	7	1	2	6 Windows
								1 Door
NO	NO	N/A	N/A	NO	NO	YES	NO	NO
			Ι	nspected				

- There was water damage on the wood on the left at the base of the convector unit near the door.
- The indoor air quality should not pose health or environmental concerns, as the total fungal ecology was 120 spores/M<sup>3</sup> of breathable air space.

#### Recommendations

• Remove and replace the water damaged wood at the base of the convector unit.

Location	IAQ Sample #	Swab	R/H	Temp	CO2	Co	Cubic f	eet of air.
Library	2434294	N/A	23.6%	75.2°	1,023	0.00	6,	800
			Ι	nspected				
Ceiling Tiles	Walls	Teachers Desk	Children's Desk	Tables	Cabinets Shelving	Convector	Window Units	Windows
1x1	CMU	1	0	4	4	5	1	7
NO	NO	NO	N/A	NO	NO	NO	NO	YES
			Obse	rvation N	lotes			
	U		site, the wind		-			

- The Carbon Dioxide (CO2) level in this room was elevated at 1,023 ppm (parts per million).
- The indoor air quality should not pose health or environmental concerns, as the total fungal ecology was 360 spores/M<sup>3</sup> of breathable air space.

#### Recommendations

- Make the necessary repairs to allow the windows to be opened and closed.
- To reduce Carbon Dioxide (CO2) levels, increase air exchange within this classroom. Ventilating or circulating the air with a fan will also reduce Carbon Dioxide (CO2) levels.

Location	IAQ	Swab	R/H	Temp	CO2	Со	Cubic f	eet of air.
	Sample #							
23	2434295	N/A	32.4%	73.9°	2,322	0.00	9,	450
			Ι	inspected				
Ceiling	Walls	Teachers	Children's	Tables	Cabinets	Convector	Window	Windows
Tiles		Desk	Desk		Shelving		Units	
2x4	CMU	1	27	5	4	1	1	8
NO	NO	NO	NO	NO	YES	YES	NO	NO
			Obse	rvation N	Notes			

• The heat has been working on and off, and makes a loud noise when it does work, according to the teacher on site.

- There was visible suspected microbial growth in sink cabinet.
- The Carbon Dioxide (CO2) level in this room was elevated at 2,322 ppm (parts per million).
- The indoor air quality should not pose health or environmental concerns, as the total fungal ecology was 40 spores/M<sup>3</sup> of breathable air space.

## Recommendations

- Implement the warranted repairs to get the convector unit functioning properly.
- To reduce Carbon Dioxide (CO2) levels, increase air exchange within this classroom. Ventilating or circulating the air with a fan will also reduce Carbon Dioxide (CO2) levels.
- HEPA vacuum, then damp-wipe the sink cabinetry with an anti-microbial agent to remove water staining and suspected microbial contamination.
- Ensure there are no active leaks from the sink.

Location	IAQ Sample #	Swab	R/H	Temp	CO2	Со	Cubic f	eet of air.
20	2434296	N/A	29.8%	73.5°	1,774	0.00	9,	,900
			Ι	inspected				
Ceiling	Walls	Teachers	Children's	Tables	Cabinets	Convector	Window	Windows
Tiles		Desk	Desk		Shelving		Units	
2x4	CMU	2	12	3	3	1	1	8
NO	NO	NO	NO	NO	YES	NO	NO	NO
			Obse	rvation N	lotes			
<ul><li>There</li><li>The </li></ul>	e was visible Carbon Diox	suspected n ide (CO2) le		wth in the om was e	sink cabine levated at 1	et. ,774 ppm (pa concerns, as t	1	· ·
	40 spores/M <sup>3</sup>		le air space.					
			Reco	mmenda	tions			
• Clear	n convector u	unit fins with	n an antimicro	obial to re	move dust	and debris.		
• LIED	A	an dama w	معامم منساح	a <b>la</b> : ua a fuera a	with an anti	microhiolog	ant to mamor	

- HEPA vacuum, then damp-wipe the sink cabinetry with an anti-microbial agent to remove water staining and suspected microbial contamination.
- Ensure there are no active leaks from the sink.
- To reduce Carbon Dioxide (CO2) levels, increase air exchange within this classroom. Ventilating or circulating the air with a fan will also reduce Carbon Dioxide (CO2) levels.

Location	IAQ	Swab	R/H	Temp	CO2	Со	Cubic f	eet of air.
	Sample #							
T5	2434297	N/A	32.4%	72.8°	1,562	0.00	5,	000
			Ι	inspected	,			
Ceiling	Walls	Teachers	Children's	Tables	Cabinets	Convector	Wall	Windows/
Tiles		Desk	Desk		Shelving		Mounted	Doors
					_		Units	
2x4	VOG	1	27	2	3	0	2	8 Windows
								2 Doors
YES	NO	NO	NO	NO	NO	N/A	NO	NO
			Ohan	A! N	T. A			

## **Observation Notes**

- There were four water stained ceiling tiles.
- There was dust and debris on the wall-mounted A/C units.
- The Carbon Dioxide (CO2) level in this room was elevated at 1,562 ppm (parts per million).
- The indoor air quality should not pose health or environmental concerns, as the total fungal ecology was 160 spores/M<sup>3</sup> of breathable air space.

## Recommendations

- Remove, discard, and replace the four water stained ceiling tiles.
- Clean wall-mounted units with an antimicrobial to remove dust and debris.
- To reduce Carbon Dioxide (CO2) levels, increase air exchange within this classroom. Ventilating or circulating the air with a fan will also reduce Carbon Dioxide (CO2) levels.

Location	IAQ	Swab	R/H	Temp	CO2	Со	Cubic feet of air.				
	Sample #										
Outside	2434290		23.6%	58.1°							
Observation Notes											
• The	total fungal e	cology in th	e outdoor cor	ntrol samr	ole was 80 s	pores/M <sup>3</sup> of	breathable air space.				

#### **Interpretation of Lab Results**

In the enclosed Air Cassette Analysis report, you will notice Fungal Identification, which is the genera detected in the breathable airspace inside, and outside. The Raw count is the actual number of spores counted on the slide, and the Count/m3 are the spores per cubic meter of air. The other particles are non-living particles such as dander, mycelial fragments, pollens, etc.

For humans to be exposed indoors, fungal spores, fragments, or metabolites must be released into the air and inhaled, physically contacted (dermal exposure), or ingested. Whether symptoms develop in people exposed to fungi depends on the nature of the fungal material (e.g., allergenic, toxic, or infectious), the amount of exposure, and the susceptibility of exposed persons.

Susceptibility varies with genetic predisposition (e.g., allergic reactions do not always occur in all individuals), age, state of health, and concurrent exposures.

#### Air Sampling Lab Results



Analyst: Goodwin, Aaron

Name: Environmental Solutions, Inc Address: 534-A Deale Road Deale, MD 20751 Phone: 410-867-6262

Project Number: 6700 Glenn Dale Rd. P.O. Number: JZB Project Name: Glenn Dale Elementary School Collected Date: 4/2/2019 Received Date: 4/3/2019 4:56:00 PM

SanAir ID Number 19015591 FINAL REPORT 4/5/2019 2:33:47 PM

#### **Air Cassette Analysis**

								ND = None D	etected, Bla	nk spaces indicate no s	pores detected.	
SanAir ID Number	190	15591-001		190	15591-002		190	15591-003		19	015591-004	
Analysis Using STL		107C			107C			107C			107C	
Sample Number		2434292			2434293			2434294			2434295	
Sample Identification	R	oom #10		1	Room #3			Library		1	Room #23	
Sample Type	Air Cas	sette - Micro-5		Air Cas	sette - Micro-5		Air Cas	sette - Micro-5		Air Ca	ssette - Micro-5	
Volume		25 Liters			25 Liters			25 Liters			25 Liters	
Analytical Sensitivity	40	Count/M <sup>3</sup>		40	Count/M <sup>3</sup>		40	Count/M <sup>3</sup>		40	) Count/M <sup>3</sup>	
Background Density		1+			2+			2+			2+	
Other	Raw Count	Count/M <sup>3</sup>	%	Raw Count	Count/M <sup>3</sup>	%	Raw Count	Count/M <sup>a</sup>	%	Raw Count	Count/M <sup>a</sup>	%
Dander	36	1440	n/a	105	4200	n/a	77	3080	n/a	80	3200	n/a
Fibers				5	200	n/a	7	280	n/a	4	160	n/a
Mycelial Fragments				2	80	n/a				3	120	n/a
Fungal Identification	Raw Count	Count/M <sup>3</sup>	%	Raw Count	Count/M <sup>3</sup>	%	Raw Count	Count/M <sup>3</sup>	%	Raw Count	Count/M <sup>3</sup>	%
Ascospores				1	40	33						
Aspergillus/Penicillium							7	280	78			
Basidiospores										1	40	>99
Bispora species												
Cladosporium species				1	40	33	2	80	22			
Smuts/Myxomycetes				1	40	33						
TOTAL				3	120		9	360		1	40	

Signature:

Chan Hach :-

Date: 4/5/2019

Reviewed: Johnston Wlan

Date: 4/5/2019

1551 Oakbridge Dr. Suite B, Powhatan, VA 23139 | 804.897.1177 | Fax: 804.897.0070 | www.SanAir.com | IAQ@SanAir.com

Page 2 of 5



Name: Environmental Solutions, Inc Address: 534-A Deale Road Deale, MD 20751 Phone: 410-867-6262

Analyst: Goodwin, Aaron

Project Number: 6700 Glenn Dale Rd. P.O. Number: JZB Project Name: Glenn Dale Elementary School Collected Date: 4/2/2019 Received Date: 4/3/2019 4:56:00 PM SanAir ID Number 19015591 FINAL REPORT 4/5/2019 2:33:47 PM

#### Air Cassette Analysis

SanAir ID Number	190	15591-005		19015591-006			190				
Analysis Using STL		107C			107C			107C			
Sample Number		2434296			2434297			2434291			
Sample Identification		oom #20			T5			oor Control			
Sample Type	Air Cas	Air Cassette - Micro-5		Air Cas	sette - Micro-5		Air Cas	sette - Micro-5			
Volume		25 Liters			25 Liters			25 Liters			
Analytical Sensitivity		Count/M <sup>3</sup>			Count/M <sup>3</sup>			Count/M <sup>3</sup>			
Background Density	2+		2+			2+					
Other	Raw Count	Count/M <sup>a</sup>	%	Raw Count	Count/M <sup>a</sup>	%	Raw Count	Count/M <sup>a</sup>	%		
Dander	89	3560	n/a	86	3440	n/a	117	4680	n/a		
ibers	7	280	n/a	2	80	n/a	10	400	n/a		
Aycelial Fragments							1	40	n/a		
ungal Identification	Raw Count	Count/M <sup>a</sup>	%	Raw Count	Count/M <sup>a</sup>	%	Raw Count	Count/M <sup>3</sup>	%		
Ascospores											
spergillus/Penicillium				2	80	50	2	80	>99		
Basidiospores											
lispora species				2	80	50					
ladosporium species	1	40	>99								
muts/Myxomycetes				2007							
OTAL	1	40		4	160		2	80			

Signature:

Now Techi,- Date: 4/5/2019

Reviewed: Johnsten Wlan

Date: 4/5/2019

1551 Oakbridge Dr. Suite B, Powhatan, VA 23139 | 804.897.1177 | Fax: 804.897.0070 | www.SanAir.com | IAQ@SanAir.com

Page 3 of 5



Name: Environmental Solutions, Inc Address: 534-A Deale Road Deale, MD 20751 Phone: 410-867-6262 SanAir ID Number **19015591** FINAL REPORT 4/5/2019 2:33:47 PM

Project Number: 6700 Glenn Dale Rd. P.O. Number: JZB Project Name: Glenn Dale Elementary School Collected Date: 4/2/2019 Received Date: 4/3/2019 4:56:00 PM

#### **Organism Descriptions**

The descriptions of the organisms presented are derived from various reference materials. The laboratory report is based on the data derived from the samples submitted and no interpretation of the data, as to potential, or a ctual, health effects resulting from exposure to the numbers of organisms found, can be made by laboratory personnel. Any interpretation of the potential health effects of the presence of this organism must be made by qualified professional personnel with first hand knowledge of the sample site, and the problems associated with that site.

**Dander** - Comprised of human and/or animal skin cells. Counts may be higher in carpeted rooms and in rooms with more traffic. *Health Effects*: May cause allergies.

Fibers - This category can include clothing, carpet, and insulation fibers.

Mycelial Fragments - A mycelium (plural = mycelia) is the "body" of a fungus. It is a collective term for hyphae ( singular = hypha), which are the tubular units of the mycelium usually composed of chitin. The terms hyphae and mycelial fragments are used interchangeably. [This information was referenced from the mycology text "The Fifth Kingdom"]In some cases a fungal identification cannot be obtained due to lack of sporulation. Only the mycelial fragments are present, and cannot be identified without the distinguishing characteristics of the spores or the structures they grow from. *Health Effects:* Allergic reactions may occur in the presence of spores (conidia) or mycelial/hyphal fragments.

Ascospores - From the fungal Subphylum Ascomycotina. Ascospores are ubiquitous in nature and are commonly found in the outdoor environment. This class contains the "sac fungi" and yeasts. Some ascospores can be identified by spore morphology, however; some care should be excercised with regard to specific identification. They are identified on tape lifts and non-viable analysis by the fact that they have no attachment scars and are sometimes enclosed in sheaths with or without sacs. Ascomycetes may develop both sexual and asexual stages. Rain and high humidity may help asci to release, and dispurse ascospores, which is why during these weather conditions there is a great increase in counts. *Health Effects:* This group contains possible allergens.

Aspergillus/Penicillium - These spores are easily aerosolized. Only through the visualization of reproductive structures can the genera be distinguished. Also included in this group are the spores of the genera Acremonium, Phialophora, Verticillium, Paecilomyces, etc. Small, round spores of this group lack the necessary distinguishing characteristics when seen on non-viable examination.

Health Effects: Can cause a variety of symptoms including allergic reactions. Most symptoms occur if the individual is immunocompromised in some way (HIV, cancer, etc). Both Penicillium and Aspergillus spores share similar morphology on non-viable analysis and therefore are lumped together into the same group.

**Basidiospores** - From the Subphylum Basidiomycotina which contains the mushrooms, shelf fungi, and a variety of other macrofungi. They are saprophytes, ectomycorrhizal fungi or agents of wood rot, which may destroy the structure wood of buildings. It is extremely difficult to identify a specific genera of mushrooms by using standard culture plate techniques. Some basidiomycete spores can be identified by spore morphology; however, some care should be exercised with regard to specific identification. The release of basidiospores is dependant upon moisture, and they are dispersed by wind. *Health Effects:* Many have the potential to produce a variety of toxins. Members of this group may trigger Type I and III fungal hypersensitivity reactions. Rarely reported as opportunistic pathogens.

**Bispora species** - Bispora is a ubiquitous anamorphic fungus and may be isolated from decaying wood. *Health Effects*: There has been no known research on the health effects, toxicity, or allergens to this fungi. *References*: C.J. K. Wang, R.A. Zabel, Identification Manual for Fungi from Utility Poles in the Eastern United States, American Type Culture Collection 1990

Page 4 of 5



Name: Environmental Solutions, Inc Address: 534-A Deale Road Deale, MD 20751

Phone: 410-867-6262

SanAir ID Number 19015591 FINAL REPORT 4/5/2019 2:33:47 PM

Project Number: 6700 Glenn Dale Rd. P.O. Number: JZB Project Name: Glenn Dale Elementary School Collected Date: 4/2/2019 Received Date: 4/3/2019 4:56:00 PM

## **Organism Descriptions**

The descriptions of the organisms presented are derived from various reference materials. The laboratory report is based on the data derived from the samples submitted and no interpretation of the data, as to potential, or actual, health effects resulting from exposure to the numbers of organisms found, can be made by laboratory personnel. Any interpretation of the potential health effects of the presence of this organism must be made by qualified professional personnel with first hand knowledge of the sample site, and the problems associated with that site.

Cladosporium species - The most commonly identified outdoor fungus. The outdoor numbers are reduced in the winter and are often high in the summer. Often found indoors in numbers less than outdoor numbers. It is commonly found on the surface of fiberglass duct liner in the interior of supply ducts. A wide variety of plants are food sources for this fungus. It is found on dead plants, woody plants, food, straw, soil, paint and textiles. Often found in dirty refrigerators and especially in reservoirs where condensation is collected, on moist window frames it can easily be seen covering the whole painted area with a velvety olive green layer.

Health Effects: It is a common allergen. It can cause mycosis. Common cause of extrinsic asthma (immediate-type hypersensitivity: type I). Acute symptoms include edema and bronchiospasms, chronic cases may develop pulmonary emphysema. Illnesses caused by this genus can include phaeohyphomycosis, chromoblastomycosis, hay fever and common allergies.

References: Flannigan, Brian, Robert A. Samson, and J. David Miller, eds. Microorganisms in Home and Indoor Work Environments: Diversity, Health Impacts, Investigation, and Control. London and New York: Taylor & Francis, 2001.

Smuts/Myxomycetes - Smuts and Myxomycetes are parasitic plant pathogens. They are typically grouped together due to their Health Effects: Can produce type I fungal hypersensitivity reactions. References: Martin, G.W., C.J. Alexopoulos, and M.L. Farr. The Genera of Myxomycetes. Iowa City, Iowa: University of Iowa

Press, 1983.

1551 Oakbridge Dr. Suite B, Powhatan, VA 23139 | 804.897.1177 | Fax: 804.897.0070 | www.SanAir.com | IAQ@SanAir.com Page 5 of 5

#### **Conclusions/Recommendations**

The samples in this report do not indicate elevated concentrations of aerosolized mold spores in the breathable air space of the specific test locations.

However, several rooms still need attention. This is mainly due to water stained ceiling tiles, water damaged sink cabinetry, dust and debris, and slightly elevated levels of CO2. Please refer to all the recommendations listed above.

I hope you found our service beneficial. If you have any questions or concerns, please feel free to contact me at 410-867-6262.

Respectfully,

Jack Butcher

Zack Butcher (CIE) Environmental Solutions, Inc.



#### **Industry References**

Since the 1993 New York City Department of Health (NYCDOH) document (Assessment and remediation of *Stachybotrys Atra* in Indoor Environments) was produced, several other guidance documents have been written. This report was developed in accordance with and including:

- Fungal Contamination in Buildings: A Guide to Recognition and Management (Health Canada, 1995).
- Control of Moisture Problems Affecting Biological Indoor Air Quality (Flannigan and Morey, 1996).
- *Bioaerosols: Assessment and Control* (American Conference of Government Industrial Hygienists [ACGIH], 1999).
- <u>Guidelines on Assessment and Remediation of Fungi in Indoor Environments</u> (NYCDOH, 2000). [external link]
- Mold Remediation in Schools and Commercial Buildings (U.S. EPA, 2001).
- *Report of the Microbial Growth Task Force* (The American Industrial Hygiene Association, 2001).
- Fungal Contamination: A manual for investigation, remediation and control (BECi) 2005.
- 29 CFR 1910, Occupational Safety and Health Standards for General Industry, U.S. Department of Labor
- Institute of Inspection, Cleaning and Restoration Certification Standard IICRC S520 29 *CFR 1926, Occupational Safety and Health Standards for the Construction Industry*, U.S. Department of Labor
- 40 CFR 61, National Emission Standards for Hazardous Air Pollutants (NESHAP), U.S. Environmental Protection Agency
- ACR 2006, Assessment, Cleaning and Restoration of HVAC Systems, National Air Duct Cleaners Association, 2006\*
- ASHRAE Standards 62.1 or 62.2
- ASTM D-1653, Standard Test Methods for Water Vapor Transmission of Organic Coating Films
- *Bioaerosols: Assessment and Control,* American Conference of Governmental Industrial Hygienists, 1999
- Field Guide for Determination of Biological Contaminants in Environmental Samples, American Industrial Hygiene Association, 2005
- A Guide for Mold Remediation in Schools and Commercial Buildings, US Environmental Protection Agency, 2001 Protecting the Built Environment: Cleaning for Health, Michael A. Berry Ph.D., 1993
- *IICRC S100 Standard and Reference Guide for Professional Carpet Cleaning, Fourth Edition, Institute of Inspection, Cleaning and Restoration Certification, (S100)\**
- *IICRC S300 Standard and Reference Guide for Professional Upholstery Cleaning, First Edition, Institute of Inspection, Cleaning and Restoration Certification, (S300)\**
- ANSI/IICRC S500 Standard and Reference Guide for Professional Water Damage Restoration, Third Edition, Institute of Inspection, Cleaning and Restoration Certification, (S500)\*