

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381601757
 CustomerID: PGCS62
 CustomerPO: 608048
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 03/01/16 11:41 AM
 Analysis Date: 3/3/2016
 Collected: 2/26/2016

Project: **Heather Hills ES**

Test Site: **Heather Hills ES**
Bowie, MD 20716

Test Report: Radon in Air Test Results**Samples for EMSL Kit 139550**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
234523	Media Center	0.8	2/26/2016	2/29/2016	70	50	Customer
381601757-0001			1:04:00 PM	6:44:00 AM			

Sample Notes:

Samples for EMSL Kit 139551

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
234488	Teacher's Lounge	1.6	2/26/2016	2/29/2016	70	50	Customer
381601757-0002			1:06:00 PM	6:43:00 AM			

Sample Notes:

Samples for EMSL Kit 139552

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
235149	Room 1	0.7	2/26/2016	2/29/2016	70	50	Customer
381601757-0003			1:07:00 PM	6:45:00 AM			

Sample Notes:

235228	Room 1	0.7	2/26/2016	2/29/2016	70	50	Duplicate
381601757-0004			1:07:00 PM	6:45:00 AM			

Sample Notes:

Duplicate RPD = 0%

Samples for EMSL Kit 139553

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
235362	Room 2	0.4	2/26/2016	2/29/2016	70	50	Customer
381601757-0005			1:09:00 PM	6:46:00 AM			

Sample Notes:

Samples for EMSL Kit 139554

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
235248	Room 14	2.4	2/26/2016	2/29/2016	70	50	Customer
381601757-0006			1:10:00 PM	6:49:00 AM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381601757
 CustomerID: PGCS62
 CustomerPO: 608048
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 03/01/16 11:41 AM
 Analysis Date: 3/3/2016
 Collected: 2/26/2016

Project: **Heather Hills ES**

Test Site: **Heather Hills ES**
Bowie, MD 20716

Test Report: Radon in Air Test Results**Samples for EMSL Kit 139558**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
235154 381601757-0007	Room 4	1.1	2/26/2016 1:13:00 PM	2/29/2016 6:50:00 AM	70	50	Customer

Sample Notes:

235372 381601757-0008	Room 4	1.4	2/26/2016 1:13:00 PM	2/29/2016 6:50:00 AM	70	50	Duplicate
--------------------------	--------	-----	-------------------------	-------------------------	----	----	-----------

Sample Notes:

Duplicate RPD = 24%

Samples for EMSL Kit 139559

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
235209 381601757-0009	Room 3	0.8	2/26/2016 1:15:00 PM	2/29/2016 6:51:00 AM	70	50	Customer

Sample Notes:**Samples for EMSL Kit 139557**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
234524 381601757-0010	Room A	0.8	2/26/2016 1:19:00 PM	2/29/2016 6:54:00 AM	70	50	Customer

Sample Notes:**Samples for EMSL Kit 139556**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
235191 381601757-0011	Room B	1.4	2/26/2016 1:20:00 PM	2/29/2016 6:55:00 AM	70	50	Customer

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381601757
 CustomerID: PGCS62
 CustomerPO: 608048
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 03/01/16 11:41 AM
 Analysis Date: 3/3/2016
 Collected: 2/26/2016

Project: **Heather Hills ES**

Test Site: **Heather Hills ES**
Bowie, MD 20716

Test Report: Radon in Air Test Results**Samples for EMSL Kit 139555**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
235181	Room C	0.8	2/26/2016	2/29/2016	70	50	Customer
381601757-0012			1:22:00 PM	6:56:00 AM			

Sample Notes:

235290	Room C	0	2/26/2016	2/29/2016	70	50	Blank
381601757-0013			1:22:00 PM	6:56:00 AM			

Sample Notes:**Samples for EMSL Kit 139546**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
235179	Room D	0.4	2/26/2016	2/29/2016	70	50	Customer
381601757-0014			1:24:00 PM	6:57:00 AM			

Sample Notes:**Samples for EMSL Kit 139547**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
235137	Resource Room	1.3	2/26/2016	2/29/2016	70	50	Customer
381601757-0015			1:28:00 PM	7:00:00 AM			

Sample Notes:**Samples for EMSL Kit 139461**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
235566	A Stage	1.6	2/26/2016	2/29/2016	70	50	Customer
381601757-0016			1:30:00 PM	6:39:00 AM			

Sample Notes:

