

www.globalincusa.net

December 15, 2020

Prince Georges County Environmental Safety Office 13306 Old Marlboro Pike Upper Marlboro, MD 20772

Attention: Mr. Alex Baylor

RE: Indoor Air Quality Screening Report

Global Project Number: 20-064 School: William Wirt Middle School

Dear Mr. Baylor,

On December 9, 2020, Global Inc.'s (GLOBAL) team of Industrial Hygienists under the supervision of Certified Industrial Hygienist, Dr. Channa Bambaradeniya, conducted an Indoor Air Quality Screening at William Wirt Middle School located at 6200 Tuckerman St, Riverdale, MD 20737.

Methodology

The IAQ evaluation included a visual assessment, sampling for non-viable mold spores in air, and measurement of comfort parameters (temperature, humidity, carbon dioxide, and carbon monoxide) in randomly selected representative locations within the building. GLOBAL's inspector conducted a walkthrough with Prince Georges County Public School (PGCPS) personnel present. Rooms were selected in a random manner throughout the building so as to prevent sampling bias.

During the visual assessment of representative locations, and when noted, GLOBAL documented those areas with suspected mold growth, water intrusions, and wet conditions that have the potential to lead to mold growth. GLOBAL also noted any unusual odors. At least one microbial air sample was collected for every 10,000 Square Feet (SF) of space in the building and the analytical results for the interior spaces were compared to an outdoor (ambient) sample collected on the same day.

Microbial samples (including a field blank for quality control) were delivered under strict chainof-custody procedures were to Hayes Microbial Consulting - an AIHA EMPAT-certified laboratory in Midlothian, Virginia for analysis by microscopy. The sample chain-of-custody and laboratory report is attached.



Observations

The general observations in the six indoor locations inspected are summarized in Table 1 below:

Location	Observations
Classroom 301	Decolored ceiling tiles present
Classroom 307	No issues
Classroom 315	No issues
Classroom 211	No issues
Classroom 202	Decolored ceiling tiles present
Classroom 113	Decolored ceiling tiles present
Library	Decolored ceiling tiles present
Classroom 103	No issues
Multipurpose room	No issues

Table 1: Observations

Comfort Parameter Measurements and Mold-in-Air Sample Results

The comfort parameter measurements and status of fungal ecology is summarized in Table 2.

Temperature

The American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE) have published recommendations for year-round acceptable temperatures in Standard 55-2016 (*Thermal Environmental Conditions for Human Occupancy*). The winter comfort range is 68 to 75°F and the summer comfort range is 73 to 79°F. It is important to note that ASHRAE standards are intended as a suggested guideline as opposed to a regulation. The indoor temperature readings, were slightly above the ASHRAE Standard in classroom 315.

Relative Humidity (RH)

Relative humidity is a key factor for mold growth. Mold has the potential of growing on suitable surfaces with humidity levels above 60%. ASHRAE standard 62.1-2013 (*Ventilation for Acceptable Indoor Air Quality*) recommends a maximum indoor relative humidity of 65% to preclude the likelihood of condensation on cool surfaces encouraging mold growth. All the indoor relative humidity readings were below the ASHRAE recommended level of 65%.

Carbon Monoxide

Carbon monoxide (CO) is a colorless and odorless gas that is produced by the incomplete combustion of carbon-containing fuels. Oil, gasoline, diesel fuels, wood, coke, and coal are the

Environmental Consultants and Engineers 1818 New York Avenue Suite 217 Washington, DC 20002

www.globalincusa.net

major sources of CO. All registered CO concentrations were below the EPA National Ambient Air Quality Standard (NAAQS) of 9 ppm.

Carbon Dioxide

Under conditions of maximum occupancy, ASHRAE Standard 62.1-2013, Appendix C, infers that the acceptable carbon dioxide upper limit is the prevailing outdoor carbon dioxide concentration plus 700 parts per million (ppm). On December 9, 2020, the outdoor (ambient) carbon dioxide concentration was approximately 391 ppm so indoor concentrations should not exceed approximately 1091 ppm (700 + 391). All indoor carbon dioxide measurements were within the ASHRAE standards.

Mold-in-Air Samples

There are no definitive regulations or standardized guidelines for addressing airborne mold in an indoor setting. If building systems (ventilation, envelope) are functioning properly, the indoor fungal ecology profile should be consistent with what is encountered outdoors and the spore concentrations should be below the ambient levels. Laboratory analytical results are attached at the end of this report.

Sample Location	Temp ⁰ F	RH%	CO ppm	CO2 ppm	Normal
Standards	ASHRAE 68 to 75°F	ASHRAE <65%	NAAQS <9	ASHRAE 1091	Ecology?
Ambient	50.1	21	0	391	-
Classroom 301	66.4	27	0	467	Yes
Classroom 307	75.5	25	0	469	Yes
Classroom 315	76.3	29	0	448	Yes
Classroom 211	75.7	24	0	416	Yes
Classroom 202	75.1	24	0	428	Yes
Classroom 113	73.8	22	0	420	Yes
Library	73.1	24	0	530	Yes
Classroom 103	73.0	24	0	422	Yes
Multipurpose room	70.6	21	0	449	Yes

Table 2: Air Quality Results



www.globalincusa.net

Conclusions and Recommendations

The comfort parameters measured were within the applicable Standards for indoor comfort. No indoor air quality issues related to mold were found during the screening performed on December 9, 2020, and all mold samples were found to have a normal ecology for an indoor environment.

It has been our pleasure to conduct these IAQ Screening services for the Prince Georges County Public School system. If you have any questions, please feel free to contact us.

Regards,

Channa Bambaradeniya, Ph.D., CIH, CSP, CHMM Certified Industrial Hygienist Global, Inc. Mobile: 443-691-0455



1818 New York Avenue Suite 217 Washington, DC 20002 www.globalincusa.net

ATTACHMENT I

Air Sample Analytical Results and Chain-Of-Custody Form



#20046091

Analysis Report prepared for

Global, Inc.

1818 New York Ave. Suite 217 Washington, DC, 20002

Phone: (443) 691-0455

BB203 PGCPS Indoor Air Quality Inspections William Wirt Middle School

Collected: December 9, 2020 Received: December 10, 2020 Reported: December 10, 2020 We would like to thank you for trusting Hayes Microbial for your analytical needs! We received 11 samples by FedEx in good condition for this project on December 10th, 2020.

The results in this analysis pertain only to this job, collected on the stated date, and should not be used in the interpretation of any other job. This report may not be duplicated, except in full, without the written consent of Hayes Microbial Consulting, LLC..

This laboratory bears no responsibility for sample collection activities, analytical method limitations, or your use of the test results. Interpretation and use of test results are your responsibility. Any reference to health effects or interpretation of mold levels is strictly the opinion of Hayes Microbial. In no event, shall Hayes Microbial or any of its employees be liable for lost profits or any special, incidental or consequential damages arising out of the use of these test results.

plien N. Hoyces

Steve Hayes, BSMT(ASCP) Laboratory Director Hayes Microbial Consulting, LLC.



EPA Laboratory ID: VA01419



Lab ID: #188863



DPH License: #PH-0198

3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112

(804) 562-3435

1818 New York Ave. Suite 217 Washington, DC, 20002 (443) 691-0455

BB203 PGCPS Indoor Air Quality Inspections William Wirt Middle School

#20046091

Spore Trap, Spore Trap Blank SOP - HMC#101

Sample Number	1	WWMS-1209-01		2 WWMS-1209-02			3	WWMS-	209-03	4 WWMS-1209-04		
Sample Name	Ambient				Room 301			Room 307		Ramp 315		
Sample Volume		75.00 liter			75.00 liter			75.00 liter		75.00 liter		
Reporting Limit		13 spores/m ³			13 spores/m ³	}		13 spores/m ³		13 spores/m ³		
Background		2			2			2		2		
Fragments		ND			ND			ND			ND	
Organism	Raw Count	Count / m ³	% of Total	Raw Count	Count / m ³	% of Total	Raw Count	Count / m ³	% of Total	Raw Count	Count / m ³	% of Total
Alternaria												
Ascospores	10	133	58.8%	1	13	50.0%	1	13	100.0%	3	40	75.0%
Aspergillus Penicillium												
Basidiospores	5	67	29.4%	1	13	50.0%				1	13	25.0%
Bipolaris Drechslera												
Chaetomium												
Cladosporium	2	27	11.8%									
Curvularia												
Epicoccum												
Fusarium												
Memnoniella												
Myxomycetes												
Pithomyces												
Stachybotrys												
Stemphylium												
Torula												
Ulocladium												
Total	17	227	100%	2	26	100%	1	13	100%	4	53	100%
Water Damage Indicator	r	Common Allergen			Slightly Higher than Baseline		Significantly Higher than Baseline			Ratio Abnormality		
		Collected: Dec 9	. 2020	Rece	Beceived: Dec 10, 2020			Benorted Dec 10, 2020				
	ES	Project Analyst: Ramesh Poluri,	PhD P. K	Zamer	She	Date: 12 - 10 - 20	Reviewe 20 Steve H	ed By: layes, BSMT	ttephen 1	1. Hoyes	Date:	D - 2020

3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112

(804) 562-3435

contact@hayesmicrobial.com

Page: **2** of **6**

1818 New York Ave. Suite 217 Washington, DC, 20002 (443) 691-0455

BB203 PGCPS Indoor Air Quality Inspections William Wirt Middle School

#20046091

Spore Trap, Spore Trap Blank SOP - HMC#101

Sample Number	5	WWMS-	1209-05	6	WWMS-	1209-06	7	WWMS-	1209-07	8	WWMS-	1209-08	
Sample Name		Room 211		Room 202				Room 113		Library			
Sample Volume	/olume 75.00 liter				75.00 liter			75.00 liter		75.00 liter			
Reporting Limit		13 spores/m ³	1		13 spores/m ³	1		13 spores/m ³	1	13 spores/m ³			
Background		2			2			2			2		
Fragments		ND			ND			ND			ND		
Organism	Baw Count	Count / m ³	% of Total	Baw Count	Count / m ³	% of Total	Baw Count	Count / m ³	% of Total	Baw Count	Count / m ³	% of Tota	
Alternaria	naw count		% 01 10tai			% 01 10tai		count / m	78 01 10tai	naw count		~ 01 10ta	
Ascospores	2	27	66.7%	1	13	33.3%	1	13	50.0%	1	13	50.0%	
Aspergillus/Penicillium			001110	· · ·		00.010	· · ·		00.0%	· · ·			
Basidiospores	1	13	33.3%										
BipolarisIDrechslera													
Chaetomium													
Cladosporium										1	13	50.0%	
Curvularia													
Epicoccum							1	13	50.0%				
Fusarium													
Memnoniella													
Myxomycetes				2	27	66.7%							
Pithomyces													
Stachybotrys													
Stemphylium													
Torula													
Ulocladium													
Total	3	40	100%	3	40	100%	2	26	100%	2	26	100%	
Water Damage Indicato	r	Common Allergen			Slightly Higher than Baseline		Significantly Higher than Baseline			Ratio Abnormality			
		Collected: Dec 9	, 2020	Rece	eived: Dec 10, 2 0	020	Reported:	Dec 10, 2020					
	ES	Project Analyst: Ramesh Poluri,	PhD P.F	Came	Shy	Date: 12 - 10 - 20 2	Review 20 Steve H	ed By: layes, BSMT 📈	Itephen 1	1. Hoyes	Date:	D - 2020	

3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112

(804) 562-3435

contact@hayesmicrobial.com

Page: 3 of 6

1818 New York Ave. Suite 217 Washington, DC, 20002 (443) 691-0455

BB203

PGCPS Indoor Air Quality Inspections William Wirt Middle School

#20046091

Spore Trap, Spore Trap Blank SOP - HMC#101

Sample Number	9	WWMS-1	209-09	10	WWMS-1	209-10	11	F	В			
Sample Name	Room 103				M.P.R.			Field Blank				
Sample Volume		75.00 liter			75.00 liter			0.00 liter				
Reporting Limit		13 spores/m ³			13 spores/m ³			1 spore/m ³				
Background		2			2			NBD				
Fragments		ND			ND			ND				
Organism	Raw Count	Count / m ³	% of Total	Baw Count	Count / m ³	% of Total	Baw Count	Count / m ³	% of Total			
Alternaria												
Ascospores	2	27	40.0%	1	13	20.0%						
Aspergillus Penicillium												
Basidiospores												
Bipolaris Drechslera												
Chaetomium												
Cladosporium				3	40	60.0%						
Curvularia												
Epicoccum												
Fusarium												
Memnoniella												
Myxomycetes	3	40	60.0%	1	13	20.0%						
Pithomyces												
Stachybotrys												
Stemphylium												
Torula												
Ulocladium												
Total	5	67	100%	5	66	100%	ND	ND				
Water Damage Indicator	or Common Allergen				Slightly Higher than Baseline			Significantly Higher than Baseline			Ratio Abnorm	ality
		Collected: Dec 9	, 2020	Rece	eived: Dec 10, 20	020	Reported:	Dec 10, 2020				

Date:

12 - 10 - 2020



3005 East Boundary Terrace, Suite F. Midlothian, VA. 23112

ame

contact@hayesmicrobial.com (804) 562-3435

Steve Hayes, BSMT Stephen 71. Payes

Reviewed By:

12 - 10 - 2020

Date:

Page: 4 of 6

1818 New York Ave. Suite 217 Washington, DC, 20002 (443) 691-0455

BB203 PGCPS Indoor Air Quality Inspections William Wirt Middle School

Reporting Limit	The Reporting Limit is the lowest number of spores that can be detected based on the total volume of the sample collected and the percentage of the slide that is counted. At Hayes Microbial, 100% of the slide is read so the LOD is based solely on the total volume. Raw spore counts that exceed 500 spores will be estimated.
Blanks	Results have not been corrected for field or laboratory blanks.
Background	The Background is the amount of debris that is present in the sample. This debris consists of skin cells, dirt, dust, pollen, drywall dust and other organic and non-organic matter. As the background density increases, the likelihood of spores, especially small spores such as those of Aspergillus and Penicillium may be obscured. The background is rated on a scale of 1 to 5 and each level is determined as follows:
	 NBD: No background detected due to possible pump or cassette malfunction. Recollect sample. (Field Blanks will display NBD) 1: <5% of field occluded. No spores will be uncountable. 2: 5-25% of field occluded. 3: 25-75% of field occluded. 4: 75-90% of field occluded. 5: >90% of field occluded. Suggested recollection of sample.
Fragments	Fragments are small pieces of fungal mycelium or spores. They are not identifiable as to type and when present in very large numbers, may indicate the presence of mold amplification.
Control Comparisons	There are no national standards for the numbers of fungal spores that may be present in the indoor environment. As a general rule and guideline that is widely accepted in the indoor air quality field, the numbers and types of spores that are present in the indoor environment should not exceed those that are present outdoors at any given time. There will always be some mold spores present in "normal" indoor environments. The purpose of sampling and counting spores is to help determine whether an abnormal condition exists within the indoor environment and if it does, to help pinpoint the area of contamination. Spore counts should not be used as the sole determining factor of mold contamination. There are many factors that can cause anomalies in the comparison of indoor and outdoor samples due to the dynamic nature of both of those environments.
	Blue: These molds are commonly seen in conditions of prolonged water intrusion and usually indicate a problem.
Water Damage Indicator	Green: Although all molds are potential allergens, these are the most common allergens that may be found indoors.
Common Allergen	Orange: The spore count is slightly higher than the outside count and may or may not indicate a source of contamination.
Slightly Higher than Baseline	Red: The spore count is significantly higher than the baseline count and probably indicates a source of contamination.
Significantly Higher than Baseline	Violet: The types of spores found indoors should be similar to the ones that were identified in the baseline sample. Significant increases (more than 25%) in
Ratio Abnormality	the ratio of a particular spore type may indicate the presence of abnormal levels of mold, even if the total number of spores of that type is lower in the indoor environment than it was outdoors.
Color Coding	Fungi that are present in indoor samples at levels lower than 200 per cubic meter are not color coded on the report, unless they are one of the water damage indicators.



Kenna Leonzo Global, Inc.		BB203 PGCPS Indoor Air Quality Inspections William Wirt Middle School	#20046091						
Washington, DC, 20002 (443) 691-0455			Organism Descriptions						
Ascospores	Habitat:	A large group consisting of more than 3000 species of fungi. Common plant pathogens and outdoor numbers become very high following rain. Most of the genera are indistinguishable by spore trap analysis and are combined on the report.							
	Effects:	Health affects are poorly studied, but many are likely to be allergenic.							
Basidiospores	Habitat:	A common group of Fungi that includes the mushrooms and bracket fungi. They are saprophytes and plant pathogens can cause structural damage to buildings.	. In wet conditions they						
	Effects:	Common allergens and are also associated with hypersensitivity pneumonitis.							
Cladosporium	Habitat:	One of the most common genera worldwide. Found in soil and plant debris and on the leaf surfaces of living plants. Th lower in the winter and often relatively high in the summer, especially in high humidity. The outdoor numbers often spi and evening. Indoors, it can be found growing on textiles, wood, sheetrock, moist window sills and in HVAC supply duc	e outdoor numbers are ke in the late afternoon sts.						
	Effects:	A common allergen, producing more than 10 allergenic antigens and a common cause of hypersensitivity pneumonitis							
Epicoccum	Habitat:	It is found in soil and plant litter and is a plant pathogen. It can grow indoors on a variety of substrates, including pape commonly found on wet drywall.	r and textiles and is						
	Effects:	It is a common allergen. No cases of infection have been reported in humans.							
Myxomycetes	Habitat:	Found on decaying plant material and as a plant pathogen.							
	Effects:	Some allergenic properties reported, but generally pose no health concerns to humans.							



G			S Add	mpany: <u><u><u>A</u></u> dress: <u>1818</u> <u><u>Suite</u> <u>Sc</u></u></u>	Near Vork 217 Cli 2002	Avenue Askington	<i>v£</i>	,		IP: FEDEX TE: 12-10- 3160 4410	- PAK 50 -2020 5391		MOLD 20046091
Golla	admber. BB2	.03			ections - Willia	anny am Wirt Mide	ile	Mohil	e. 2404359	2771	Email:	kennal@	Dolobalincusa net
Collector: Kenna Leonzo School											port to cha	nnah@c	zlobalincusa net
Date	Collected: 12	2/09/20		1	-huria Description				Flease en			nted Media	Types
			Identificati	All	Europel Spores			24 H		Air Cassel	tes Impact	Slides	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Spore		<u> </u>		Analysis with Dando	r Eiber and Bellen cou	nte		24	lour	Air Casset	tes Impact	Slides	
		 	Spore Trap	Analysis with Dance	r, Fiber, and Polieti Cou			24 1	lour	Rio-Tane	Tane Swah	Bulk Ana	
Direc	tiD	D	ID & Semi-		on or spores and myce			24		Bio-Tape,	Tape, Swab,	Bulk Ana	ar Plate
		U+	Direct Anal	lysis with Fully Quant	Male anh			7.02		Air Plate	Ager Plate	Swah Bull	k
Cultu	re		Identificati	on & Enumeration of	Postoria only				4y	Air Plate	Agar Plate	Swab Rul	k
		<u> </u>	Identificati	on & Enumeration of	Mald and Pactoria				ay av	Air Plate	Agar Plate S	Swab Bul	k
		05	Coliform C	on & Enumeration of				2 Day Agar Plate Swah F			Swab Bull	k	
			Total Barti	creen for Sewage Bac	Count (Does Not Inclus	de Moid)		200	40ur	Air Casse	ttes, Impact	Slides, Bi	o-Tape
Partie							Analysi		Volume			Note	s
#		er	Archie		umpic		~iiaiysi		75 1				-
	WWMS-1	1209-01	Amble	nı 201			<u> </u>		751				
2	WWWS-	1209-02	Room	301			<u> </u>		751				
3		1209-03	Room	215	· · · · · · · · · · · · · · · · · · ·				751				
4		1209-04	Ramp	<u></u>				751					
0 6		1209-05	Room	202	<u></u>		S		751		<u></u>		
		1209-00	Room	113			S		751			<u> </u>	
0		1209-07	Libran	,			<u> </u>		751	_			
0	10/0/MS_	1209-00	Room	103	·····		s		75 L				
10		1209-09	MPR	100			s		75 L				
10	FF	209-10	Field F	lank					- 080				
12	16										<u>,</u>		
12													
14													
15													
16					· · · · · · · · · · · · · · · · · · ·								
Rele	ased by:	enna l	e.nzo	Da	te: 12/9/20	Received E	By:	I	_	$\overline{\mathcal{N}}$	ĥ	C	vate: /) / 0-20
Hayes M	Aicrobial Consultin	g, LLC.	3005 East Bo	undary Terrace, Suite F.	Midlothian, VA. 23112	(804) 562-343	85 c	contact@	@hayesmicrobial	l.com			Form #20, Rev.3, March 23, 20 Chain of Custo