
November 21, 2023

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:
**COOL SPRINGS ES
MAIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
11293019	11	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	0.6 ± 0.5	2023-11-20
11293022	11	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	< 0.3	2023-11-20
11293011	2	2023-11-10 @ 12:00 pm	2023-11-13 @ 1:00 pm	< 0.3	2023-11-20
11293025	2	2023-11-10 @ 12:00 pm	2023-11-13 @ 1:00 pm	0.8 ± 0.6	2023-11-20
11293023	4	2023-11-10 @ 12:00 pm	2023-11-13 @ 1:00 pm	< 0.3	2023-11-20
11293026	MULTIPURPOSE ROOM BY STAGE	2023-11-10 @ 12:00 pm	2023-11-13 @ 1:00 pm	1.5 ± 0.6	2023-11-20
11293021	MULTIPURPOSE ROOM BY WATER FOUNTAIN	2023-11-10 @ 12:00 pm	2023-11-13 @ 1:00 pm	0.7 ± 0.5	2023-11-20

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498