

Radon test result report for:

**LANGLEY PARK MCCORMICK ES  
MAIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
11293041	12	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	< 0.3	2023-11-20
11293033	16	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	< 0.3	2023-11-20
11293034	16	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	2.1 ± 0.7	2023-11-20
11293030	19	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	3.9 ± 0.8	2023-11-20
11293042	2	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	< 0.3	2023-11-20
11293039	21	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	1.9 ± 0.7	2023-11-20
11293020	25	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	< 0.3	2023-11-20
11293027	30	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	0.6 ± 0.5	2023-11-20
11293035	5	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	1.5 ± 0.7	2023-11-20
11293040	CAFE NEAR KITCHEN ENTRANCE	2023-11-10 @ 1:00 pm	2023-11-13 @ 2:00 pm	< 0.3	2023-11-20
11293028	CAFETERIA NEAR STAGE	2023-11-10 @ 1:00 pm	2023-11-13 @ 2:00 pm	0.5 ± 0.6	2023-11-20
11293037	CAFETERIA NEAR STAGE	2023-11-10 @ 1:00 pm	2023-11-13 @ 2:00 pm	1.3 ± 0.6	2023-11-20
11293032	GYM BEHIND BASKETBALL HOOP	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	< 0.3	2023-11-20
11293024	GYM BY WATER FOUNTAIN	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	< 0.3	2023-11-20
11293031	PRINCIPALS OFFICE	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	2.4 ± 0.7	2023-11-20
11293045	PRINCIPALS OFFICE	2023-11-10 @ 12:00 pm	2023-11-13 @ 2:00 pm	1.8 ± 0.6	2023-11-20