

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381602428
 CustomerID: PGCS62
 CustomerPO: 608048
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 03/16/16 11:14 AM
 Analysis Date: 3/17/2016
 Collected: 3/11/2016

Project: **Walden Woods**

Test Site: **Walden Woods**
Clinton, MD 20735

Test Report: Radon in Air Test Results**Samples for EMSL Kit 141652**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239544 381602428-0001	Main Office	0.8	3/11/2016 5:10:00 PM	3/14/2016 7:01:00 AM	70	50	Customer

Sample Notes:

239593 381602428-0002	Main Office	0.6	3/11/2016 5:10:00 PM	3/14/2016 7:01:00 AM	70	50	Duplicate
--------------------------	-------------	-----	-------------------------	-------------------------	----	----	-----------

Sample Notes:

Duplicate RPD = 28.6%

Samples for EMSL Kit 141651

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239519 381602428-0003	Room 20	0.1	3/11/2016 5:13:00 PM	3/14/2016 7:02:00 AM	70	50	Customer

Sample Notes:**Samples for EMSL Kit 141546**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
238192 381602428-0004	Room 18	0.1	3/11/2016 5:15:00 PM	3/14/2016 7:13:00 AM	70	50	Customer

Sample Notes:

238171 381602428-0005	Room 18	0.1	3/11/2016 5:15:00 PM	3/14/2016 7:13:00 AM	70	50	Duplicate
--------------------------	---------	-----	-------------------------	-------------------------	----	----	-----------

Sample Notes:

Duplicate RPD = 0%

Samples for EMSL Kit 141695

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239461 381602428-0006	Room 13	0.6	3/11/2016 5:18:00 PM	3/14/2016 7:15:00 AM	70	50	Customer

Sample Notes:

239787 381602428-0007	Room 13	-0.2	3/11/2016 5:18:00 PM	3/14/2016 7:15:00 AM	70	50	Blank
--------------------------	---------	------	-------------------------	-------------------------	----	----	-------

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>cinnaminsonradonlab@emsl.com

EMSL Order: 381602428

CustomerID: PGCS62

CustomerPO: 608048

ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 03/16/16 11:14 AM
 Analysis Date: 3/17/2016
 Collected: 3/11/2016

Project: **Walden Woods**

Test Site: **Walden Woods**
Clinton, MD 20735

Test Report: Radon in Air Test Results**Samples for EMSL Kit 141700**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239490	Room 14	0.4	3/11/2016	3/14/2016	70	50	Customer
381602428-0008			5:19:00 PM	7:16:00 AM			

Sample Notes:**Samples for EMSL Kit 141704**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239479	Room 12	0.2	3/11/2016	3/14/2016	70	50	Customer
381602428-0009			5:21:00 PM	7:18:00 AM			

Sample Notes:**Samples for EMSL Kit 141699**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239521	Room 9		3/11/2016	3/14/2016	70	50	Customer
381602428-0010			5:22:00 PM	7:19:00 AM			

Sample Notes: Not Analyzed
 Did not receive

Samples for EMSL Kit 141698

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239423	Library	0.2	3/11/2016	3/14/2016	70	50	Customer
381602428-0011			5:24:00 PM	7:21:00 AM			

Sample Notes:

239542	Library	0.2	3/11/2016	3/14/2016	70	50	Duplicate
381602428-0012			5:24:00 PM	7:21:00 AM			

Sample Notes:**Duplicate RPD = 0%**

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381602428
 CustomerID: PGCS62
 CustomerPO: 608048
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 03/16/16 11:14 AM
 Analysis Date: 3/17/2016
 Collected: 3/11/2016

Project: **Walden Woods**

Test Site: **Walden Woods**
Clinton, MD 20735

Test Report: Radon in Air Test Results**Samples for EMSL Kit 141703**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239365	Room 8	0.4	3/11/2016	3/14/2016	70	50	Customer
381602428-0013			5:25:00 PM	7:22:00 AM			

Sample Notes:

Samples for EMSL Kit 141697

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239473	Room 6	0.6	3/11/2016	3/14/2016	70	50	Customer
381602428-0014			5:27:00 PM	7:23:00 AM			

Sample Notes:

Samples for EMSL Kit 141696

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239514	Room 110	0.9	3/11/2016	3/14/2016	70	50	Customer
381602428-0015			5:30:00 PM	7:25:00 AM			

Sample Notes:

Samples for EMSL Kit 141701

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239488	Room 101	0.6	3/11/2016	3/14/2016	70	50	Customer
381602428-0016			5:31:00 PM	7:27:00 AM			

Sample Notes:

Samples for EMSL Kit 141702

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239494	Room 108	1.1	3/11/2016	3/14/2016	70	50	Duplicate
381602428-0017			5:32:00 PM	7:29:00 AM			

Sample Notes:

239819	Room 108	1	3/11/2016	3/14/2016	70	50	Customer
381602428-0018			5:32:00 PM	7:29:00 AM			

Sample Notes:

Duplicate RPD = 9.5%

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381602428
 CustomerID: PGCS62
 CustomerPO: 608048
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 03/16/16 11:14 AM
 Analysis Date: 3/17/2016
 Collected: 3/11/2016

Project: **Walden Woods**

Test Site: **Walden Woods**
Clinton, MD 20735

Test Report: Radon in Air Test Results**Samples for EMSL Kit 141692**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239509	Room 102	0.7	3/11/2016	3/14/2016	70	50	Duplicate
381602428-0019			5:34:00 PM	7:30:00 AM			

Sample Notes:

239811	Room 102	0.6	3/11/2016	3/14/2016	70	50	Customer
381602428-0020			5:34:00 PM	7:30:00 AM			

Sample Notes:

Duplicate RPD = 15.4%

Samples for EMSL Kit 141691

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239507	Room 106	0.4	3/11/2016	3/14/2016	70	50	Customer
381602428-0021			5:36:00 PM	7:21:00 AM			

Sample Notes:**Samples for EMSL Kit 141693**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239440	Room 104	0.3	3/11/2016	3/14/2016	70	50	Customer
381602428-0022			5:37:00 PM	7:22:00 AM			

Sample Notes:**Samples for EMSL Kit 141694**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239798	Teacher's Lounge	1	3/11/2016	3/14/2016	70	50	Customer
381602428-0023			5:39:00 PM	7:24:00 AM			

Sample Notes:**Samples for EMSL Kit 141706**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239535	Room 1	0.4	3/11/2016	3/14/2016	70	50	Customer
381602428-0024			5:41:00 PM	7:26:00 AM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>cinnaminsonradonlab@emsl.com

EMSL Order:	381602428
CustomerID:	PGCS62
CustomerPO:	608048
ProjectID:	

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 03/16/16 11:14 AM
 Analysis Date: 3/17/2016
 Collected: 3/11/2016

Project: **Walden Woods**

Test Site: **Walden Woods**
Clinton, MD 20735

Test Report: Radon in Air Test Results**Samples for EMSL Kit 141707**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239492	Room 3	1.2	3/11/2016	3/14/2016	70	50	Customer
381602428-0025			5:42:00 PM	7:28:00 AM			

Sample Notes:

The radon test was performed using a liquid scintillation radon detector/s and counted on a liquid scintillation counter using approved EPA testing protocols for Radon in Air testing. The EPA recommends fixing your home if the average of two short-term tests taken in the lowest lived-in level of the home show radon levels that are equal to or greater than 4.0pCi/L.
 The EPA recommends retesting your home every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information.
 All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

Report Note

Analyst(s)

Kathryn Lickfield (24)

Laura Freeman, Interim Laboratory Manager &
 Subash Rashat, New Jersey Radiation Specialist NJ MES 10152
 or other approved signatory

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless otherwise specified. Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005. Subash Rashat certification #MES10152

Initial report from 03/22/2016 16:43:51

Please visit www.radontestinglab.com